




## Installation Guide 90D 98 - US







Mark center line on both substrates. The 90D 98 works on box joints (shown), t-section and mitered joints. Mark mounting screw centre points by measuring or with the aid of the Mark-Out Template.





Fasten each Hook with 3 x 8G screws. Ensure sufficient screw embedment in substrate.




An alternative to marking screw locations is to apply glue to the mounting faces of the Hooks to aid with placement. Line up notches in the Hooks with the marked lines them press and hold the assembled 90D in place. Allow time for glue to dry.








Install the Key remembering it only needs to travel 1 pitch for full engagement. Use the padlock symbol as a guide. The Key is also bidirectional and can be installed either end, see step 6b.



Key being installed in other end of the assembled Hooks.

## **Installation Aids**



Striplox Mark-Out Template


Developed to aid in the installation of the Striplox 90D 98, Pro 55, Mini 60 and 120.



## Striplox Liquidlox

Instant adhesive with a 15 second cure time. Liquidlox delivers a strong and reliable connection between Striplox products and most substrates.

## **Load Capacity**



Direction	Indic. Load Capacity
А	440 lb
В	145 lb
С	440 lb

- Tested using particle board and fixed with screws.
- Ensure sufficient screw embedment in substrate.